

TALBOT MACKENZIE & ASSOCIATES

CONSULTING ARBORISTS

2621 Douglas Street, Victoria, BC

Construction Impact Assessment & Tree Management Plan

PREPARED FOR: Merchant House Capital

2621 Douglas Street

Victoria, BC V8R 4M2

PREPARED BY: Talbot, Mackenzie & Associates

Noah Talbot – Consulting Arborist

ISA Certified # PN-6822A

Tree Risk Assessment Qualified

DATE OF ISSUANCE: December 16, 2020

CONTENTS

| 1. | INTR | RODUCTION | 1 | | | | | | | | |
|------|---------|--|----|--|--|--|--|--|--|--|--|
| 2. | TRE | E INVENTORY METHODOLOGY | 1 | | | | | | | | |
| 3. | | CUTIVE SUMMARY | | | | | | | | | |
| 4. | TRE | E INVENTORY DEFINITIONS | 2 | | | | | | | | |
| 5. | SITE | INFORMATION & PROJECT UNDERSTANDING | 6 | | | | | | | | |
| 6. | FIEL | D OBSERVATIONS | 6 | | | | | | | | |
| 7. | TRE | E RISK ASSESSMENT | 7 | | | | | | | | |
| 8. | CON | CONSTRUCTION IMPACT ASSESSMENT | | | | | | | | | |
| | 8.1. | Retention and Removal of Municipal Trees | 7 | | | | | | | | |
| | 8.2. | Retention and removal of onsite trees | 7 | | | | | | | | |
| | 8.3. | Tree replacement | 8 | | | | | | | | |
| 9. | IMP/ | ACT MITIGATION | 8 | | | | | | | | |
| 10. | DISC | CLOSURE STATEMENT | 11 | | | | | | | | |
| 11. | IN C | LOSING | 12 | | | | | | | | |
| 12. | REF | ERENCES | 12 | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| TAE | BLES | | | | | | | | | | |
| Tabl | e 1. Tr | ree Inventory | 4 | | | | | | | | |

APPENDICES

Appendix A Tree Management Plan (T1)

Appendix B Site Photographs

Appendix C Landscape Plans

Appendix D Site Servicing Plan

1. INTRODUCTION

Talbot Mackenzie & Associates was asked to complete a tree inventory, construction impact assessment and management plan for the trees at the following proposed project:

Site: 2621 Douglas Street

Municipality City of Victoria

Client Name: Merchant House Capital

Dates of Site Visit: October 8, 2020

Site Conditions: 1 urban lot with the existing Victoria Press building at the West side

of the property and a parking lot on the East side of the property.

Ongoing construction activity to the interior of the building.

Weather During Site Visit: Clear and sunny

The purpose of this report is to address requirements of the City of Victoria arborist report terms of reference, and Tree Preservation Bylaw No. 05-106. The construction impact assessment section of this report (section 8), is based on plans reviewed to date, including the Landscape plans (dated February 19, 2020) prepared by Murdoch De Greeff Inc) and site servicing plan (dated March 14, 2019) - prepared by JE Anderson & Associates.

2. TREE INVENTORY METHODOLOGY

For the purpose of this report, the size, health, and structural condition of trees located on the subject site and trees located on the municipal boulevard (fronting the subject site was documented). There were no private offsite trees observed with critical root zones extending onto the subject property. For ease of identification in the field, numerated metal tags were attached to the lower trunks of onsite trees (tag#'s 1898 – 1902). Trees located on the municipal frontage were not tagged (identified as NT 1 – NT 6). Each tree was visually examined on a limited visual assessment basis (level 1), in accordance with Tree Risk Assessment Qualification (TRAQ) methods (Dunster *et al.* 2017) and ISA Best Management Practices.

3. EXECUTIVE SUMMARY

Based on review of the Landscape plans and site servicing plan, 2 bylaw protected size onsite plum trees are proposed for removal due to impacts associated with the proposed new sidewalk design. An additional 1 non bylaw protected size onsite crabapple tree is proposed for removal due to due to impacts associated with the proposed new landscape design. The three trees proposed for removal were rated unsuitable for retention, due to their existing structural defects, poor rooting environment and poor soil conditions. Plum 1898 is infected with the wood decay pathogen *Ganodema applanatum*.

Two bylaw protected size onsite Japanese maple trees are located where they are possible for retention provided that the critical root zones can be adequately protected during proposed demolition and construction works. Six municipal boulevard trees are located on the Kings Road frontage, where they should be possible to protect using tree protection barriers.

4. TREE INVENTORY DEFINITIONS

Tag: Tree identification number on a metal tag attached to tree with nail or wire, generally at eye level. Trees on municipal or neighboring properties are not tagged.

NT: No tag due to inaccessibility or ownership by municipality or neighbour.

DBH: Diameter at breast height – diameter of trunk, measured in centimetres at 1.4m above ground level. For trees on a slope, it is taken at the average point between the high and low side of the slope.

- * Measured over ivy
- ~ Approximate due to inaccessibility or on neighbouring property

Dripline: Indicates the radius of the crown spread measured in metres to the dripline of the longest limbs.

Relative Tolerance Rating: Relative tolerance of the tree species to construction related impacts such as root pruning, crown pruning, soil compaction, hydrology changes, grade changes, and other soil disturbance. This rating does not take into account individual tree characteristics, such as health and vigour. Three ratings are assigned based on our knowledge and experience with the tree species: Poor (P), Moderate (M) or Good (G).

Critical Root Zone: A calculated radial measurement in metres from the trunk of the tree. It is the optimal size of tree protection zone and is calculated by multiplying the DBH of the tree by 10, 12 or 15 depending on the tree's Relative Tolerance Rating. This methodology is based on the methodology used by Nelda Matheny and James R. Clark in their book "Trees and Development: A Technical Guide to Preservation of Trees During Land Development."

- 15 x DBH = Poor Tolerance of Construction
- 12 x DBH = Moderate
- 10 x DBH = Good

To calculate the critical root zone, the DBH of multiple stems is considered the sum of 100% of the diameter of the largest stem and 60% of the diameter of the next two largest stems. It should be noted that these measures are solely mathematical calculations that do not consider factors such

as restricted root growth, limited soil volumes, age, crown spread, health, or structure (such as a lean).

Health Condition:

- Poor significant signs of visible stress and/or decline that threaten the long-term survival of the specimen
- Fair signs of stress
- Good no visible signs of significant stress and/or only minor aesthetic issues

Structural Condition:

- Poor Structural defects that have been in place for a long period of time to the point that mitigation measures are limited
- Fair Structural concerns that are possible to mitigate through pruning
- Good No visible or only minor structural flaws that require no to very little pruning

Suitability ratings are described as follows:

Rating: Suitable.

 A tree with no visible or minor health or structural defects, is tolerant to changes to the growing environment and is a possible candidate for retention provided that the critical root zone can be adequately protected.

Rating: Conditional.

A tree with good health but is a species with a poor tolerance to changes to its growing environment or
has a structural defect(s) that would require that certain measures be implemented, in order to consider it
suitable for retention (ie. retain with other codominant tree(s), structural pruning, mulching, supplementary
watering, etc.)

Rating: Unsuitable.

 A tree with poor health, a major structural defect (that cannot be mitigated using ANSI A300 standards), or a species with a poor tolerance to construction impacts, and unlikely to survive long term (in the context of the proposed land use changes).

Retention Status:

- Remove Not possible to retain given proposed construction plans
- Retain It is possible to retain this tree in the long-term given the proposed plans and information available. This is assuming our recommended mitigation measures are followed
- Retain * See report for more information regarding potential impacts

Table 1. Tree Inventory

| Location Tag (On, Off, | | | | Name | | | | Critical | | Condition | | Retention | | | | |
|---------------------------|---------|------------|------------------|---------------------------------|-------------------------------------|----------|-----------|-------------------------|---------------------|-----------|------------|-------------------------------|--------------------|---|--|------------------|
| or ID # | Shared, | Surveyed ? | Bylaw protected? | Common | Botanical | dbh (cm) | Ht (m) | root zone radius (m) | Dripline radius (m) | Health | Structural | Suitability (onsite trees) | Relative tolerance | Remarks | Tree Retention Comments | Retention status |
| NT1 | City | No | Yes | Upright European hornbeam | Carpinus betulus 'fastigiate' | 5 | 4 | 0.53 | 0.5 | Good | Good | | Good | Located on municipal boulevard, juvenile tree. | Project arborist to supervise any excavation required within the critical root zone. | Retain |
| NT2 | City | No | Yes | English hawthorn | Craetagus laevigata | 9 | 4 | 0.95 | 1.5 | Fair | Fair | | Good | Located on municipal boulevard, weed water damage at root collar. | Project arborist to supervise any excavation required within the critical root zone. | Retain |
| NT3 | City | No | Yes | Upright European hornbeam | Carpinus betulus 'fastigiate' | 4 | 4 | 0.42 | 0.5 | Good | Good | | Good | Located on municipal boulevard, juvenile tree. | Project arborist to supervise any excavation required within the critical root zone. | Retain |
| NT4 | City | Yes | Yes | English hawthorn | Craetagus laevigata | 25 | 6 | 2.63 | 3 | Fair/good | Fair/good | | Good | Located on municipal boulevard, beginning to conflict with overhead utilities, multiple leaders form at 2m above grade - no major weaknesses visible at stem unions. | Project arborist to supervise any excavation required within the critical root zone. | Retain |
| NT5 | City | Yes | Yes | English hawthorn | Craetagus Iaevigata | 30 | 6 | 3.15 | 3 | Fair/good | Fair/good | | Good | Located on municipal boulevard, beginning to conflict with overhead utilities, codominant leaders form at 2m above grade - no major weaknesses visible at stem union, historic pruning wounds with associated surface decay. | Project arborist to supervise any excavation required within the critical root zone. | Retain |
| NT6 | City | Yes | Yes | English hawthorn | Craetagus Iaevigata | 31 | 6 | 3.26 | 3 | Fair/good | Fair/good | | Good | Located on municipal boulevard, beginning to conflict with overhead utilities, multiple leaders form at 2m above grade - no major weaknesses visible at stem unions, pruning and small tear out wounds with associated surface decay. | Project arborist to supervise any excavation required within the critical root zone. | Retain |
| | On | Yes | Yes | Purple leaf plum | Prunus cerasifera | 41 | 7 | 4.31 | 4 | Fair/good | Fair/poor | Unsuitable | Good | Located on municipal property, heavily compacted soils surrounding root collar, growing within confined area (existing concrete retaining wall to East, existing concrete sidewalk to West, existing brick pavers to North and South), Ganodema applanatum fruiting bodies attached to root collar, suckering from base, injuries to topsides of surface roots with associated decay. | Located within footprint of the proposed new sidewalk. | Remove |
| 1899 | On | Yes | Yes | Purple leaf | Prunus cerasifera | 32 | 7 | 3.36 | 4 | | Fair/poor | Unsuitable | Good | Located on municipal property, heavily compacted soils surrounding root collar, growing within confined area (existing concrete retaining wall to East, existing concrete sidewalk to West, existing brick pavers to North and South), trunk leaning to East - corrected, injuries to topsides of surface roots, asymmetric crown on West side due to sidewalk clearance pruning. | Located within footprint of the proposed new sidewalk. | Remove |

| Tag | Location (On, Off, | | | Name | | | | Critical | | Condition | | Retention | | | | |
|-------|-----------------------|------------|------------------|-------------------|---------------|--|-----------|-------------------------|---------------------|-----------|------------|-------------------------------|--------------------|---|--|------------------|
| or ID | Shared, | Surveyed ? | Bylaw protected? | Common | Botanical | dbh (cm) | Ht (m) | root zone radius (m) | Dripline radius (m) | Health | Structural | Suitability (onsite trees) | Relative tolerance | Remarks | Tree Retention Comments | Retention status |
| 1900 | On | No | No | Crabapple | Malus sp. | 14 | 5 | 1.47 | 3 | Fair | Fair/poor | Unsuitable | Good | Non bylaw protected size tree, growing within confined root environment - existing retaining wall .3m from North side of root collar, existing concrete planter within .3m of South/East/West side of root collar, sucker it from base, pruning wounds with associated surface decay, shaded by building. | Shown on landscape plan to be removed and replaced with a new shrub. | Remove |
| 1901 | On | Yes | Yes | Japanese maple | Acer palmatum | 12,6,14,14 ,11,14 | 5 | 3.23 | 4 | Good | Fair | Suitable | Good | Located within landscape bed - on slope, confined root system on South side - existing retaining wall within .2m of root collar, heavily surface rooted on embankment, multiple stems form at 3m above grade - narrow angles of attachment. | *Existing concrete stairway within critical root zone proposed for removal. Project arborist to supervise all excavation and fill placement required within the critical root zone. | Retain* |
| 1902 | On | Yes | Yes | Japanese maple | Acer palmatum | 7,7,13,13, 10,10,5,7, 12,12,16,6 | 5 | 3.26 | 4 | Good | Fair | Suitable | Good | Located within landscape bed - on slope, confined root system on South side - existing retaining wall within .2m of root collar, heavily surface rooted on embankment, multiple stems form at3m above grade - narrow angles of attachment. | *Existing concrete stairway within critical root zone proposed for removal. Project arborist to supervise all excavation and fill placement required within the critical root zone. | Retain* |

*CRZ calculated above and drawn as follows on Tree Management Plan (T1): CRZ + 0.5 * d.b.h. (drawn from the center of the stem)

5. SITE INFORMATION & PROJECT UNDERSTANDING

The development site consists of a large City lot (2621 Douglas Street), in Victoria, B.C., which has the existing Victoria Press building at the West side of the property and a parking lot on the East side of the property. Ongoing construction activity was occurring within the interior of the building at the time of our tree inventory. It is our understanding that the proposal is to renovate the West side of the exterior of the building and the existing planting areas, construction of a new sidewalk along the West side of the property, and installation of new hard landscape features, new trees and new shrubs.

Below is a general observation of the tree resource, as it appeared at the time of our site visit:

6. FIELD OBSERVATIONS

The onsite tree resource consists of 4 bylaw protected trees (tag #'s 1898, 1899, 1901 & 1902), located between the existing building and the West property boundary. One non-bylaw protected crabapple (tag# 1900) was also observed within an existing planter near the front of the building. Six boulevard trees (NT1 – NT6) were observed on the Kings Road frontage (see photographs 1 & 2 – appendix B). The onsite plum trees are growing in a confined planting area, with heavy foot traffic, resulting in compacted soils and injuries to the topsides of the surface roots (see photograph 3,4 and 5 – appendix B). The Onsite crabapple and Japanese maples are also growing in confined planting locations, in the existing planters (see photograph 6,7 and 8 – appendix B).



figure 1: Site context air photo: The boundary of the subject site is outlined in Yellow.

7. TREE RISK ASSESSMENT

During our October 08, 2020 site visit and in conjunction with the tree inventory, onsite trees were assessed for risk, on a limited visual assessment basis (level 1), and in the context of the existing land uses. The time frame used for the purpose of our assessment is one year (from the date of the October 08, 2020 tree inventory). Unless otherwise noted herein, we did not conduct a detailed (level 2) or advanced (level 3) risk assessment, such as resistograph testing, increment core sampling, aerial examinations, or subsurface root/root collar examinations.

Existing Land Uses

We did not observe any trees that were deemed to be moderate, high or extreme risk (in the context of the existing land uses, that would require hazard abatement to eliminate present and/or future risks (within a 1-year timeframe). Targets considered during this TRAQ assessment include: occupants of the existing onsite building (constant use), occupants of vehicles travelling on Douglas Street and Kings Road (frequent use), pedestrians travelling along existing sidewalks (frequent use), hydro lines (constant use).

8. CONSTRUCTION IMPACT ASSESSMENT

8.1. RETENTION AND REMOVAL OF MUNICIPAL TREES

The following municipal trees (indicated by ID #) are located where they is possible for retention providing that their critical root zones are adequately protected during construction. The project arborist must be onsite to supervise and excavation or fill placement required within the critical root zone (shown on the tree management plan (T1) in *appendix A*):

Retain and protect 6 municipal trees

NT1, NT2, NT3, NT4, NT5, NT6

*Note that the municipality will need to provide consent, prior the removal of any trees that are located on Municipal property.

8.2. RETENTION AND REMOVAL OF ONSITE TREES

The following <u>Bylaw protected</u> size onsite trees (indicated by tag #) are located where they are possible for retention providing that their critical root zones are adequately protected during construction. The project arborist must be onsite to supervise and excavation or fill placement required within their critical root zones (shown on the tree management plan (T1) in *appendix A*):

Retain and protect 2 bylaw protected onsite trees

1901, 1902.

The following <u>bylaw protected size</u> onsite trees (indicated by tag #) are located where they are in conflict with the proposed new sidewalk design and are proposed for removal:

Remove 2 bylaw protected onsite trees

1898, 1899.

The following <u>non bylaw protected size</u> onsite tree (indicated by tag #) is located where it is in conflict with the proposed new landscape design and is proposed for removal:

Remove 1 non bylaw protected onsite tree

1900

8.3. TREE REPLACEMENT

Pursuant to City of Victoria Tree Preservation Bylaw No. 05-106, the tree replacement calculations are as follows:

| Quantity of Existing | # of | # of Trees | Replacement | Replacement | Replacement | Replacement | | | | |
|-----------------------|----------|------------|-------------|-------------|-------------|-------------|--|--|--|--|
| bylaw protected trees | Trees | Removed | Tree Ratio | Trees | Trees | Trees in | | | | |
| | Retained | | | Required | Proposed | Deficit | | | | |
| Onsite | | | | | | | | | | |
| 4 | 2 | 2 | 2:1 | 4 | Refer to | Refer to | | | | |
| | | | | | Landscape | Landscape | | | | |
| | | | | | plans | plans | | | | |
| | | City own | ed Trees | | | | | | | |
| 6 | 6 | 0 | 2:1 | N/A | N/A | N/A | | | | |
| | • | Private of | fsite Trees | | | | | | | |
| 0 | N/A | N/A | 2:1 | N/A | N/A | N/A | | | | |
| | | | Total: | <u>4</u> | Refer to | Refer to | | | | |
| | | | | | Landscape | Landscape | | | | |
| | | | | | plans | plans | | | | |

Based on bylaw criteria, 4 replacement trees are required to replace the 2 onsite trees that are proposed for removal (2:1 ratio). Refer to the Landscape plan (prepared by others) for replacement tree planting locations and specifications. If the site cannot accommodate the required quantity of replacement trees, the deficit will be compensated to the City via a cash in lieu payment by the owner. Current arboricultural best management practices and BCSLA/BCLNA standards apply to; quality, root ball, health, form, handling, planting, guying/staking and establishment care of replacement trees.

9. IMPACT MITIGATION

Tree Protection Barrier: The areas, surrounding the trees to be retained should be isolated from the construction activity by erecting protective barrier fencing (see *Appendix A* for municipal barrier specifications). Where possible, the fencing should be erected at the perimeter of the critical root zone. The barrier fencing to be erected

must be a minimum of 4 feet in height, of solid frame construction that is attached to wooden or metal posts. A solid board or rail must run between the posts at the top and the bottom of the fencing. This solid frame can then be covered with flexible snow fencing. The fencing must be erected prior to the start of any construction activity on site (i.e. demolition, excavation, construction), and remain in place through completion of the project. Signs should be posted around the protection zone to declare it off limits to all construction related activity. The project arborist must be consulted before this fencing is removed or moved for any purpose.

Arborist Supervision: All excavation occurring within the critical root zones of protected trees should be completed under supervision by the project arborist. Any severed or severely damaged roots must be pruned back to sound tissue to reduce wound surface area and encourage rapid compartmentalization of the wound. In particular, the following activities should be completed under the direction of the project arborist:

- Excavation to remove the existing concrete stairway within the critical root zone of maple 1901
- Excavation to remove the existing concrete stairway within the critical root zone of maple 1902
- Any fill addition within the critical root zones of maple 1901 and 1902.
- Any excavation to upgrade of install new underground utilities within critical root zones of bylaw protected trees or trees located on municipal property.

Methods to Avoid Soil Compaction: In areas where construction traffic must encroach into the critical root zones of trees to be retained, efforts must be made to reduce soil compaction where possible by displacing the weight of machinery and foot traffic. This can be achieved by one of the following methods:

- Installing a layer of hog fuel or coarse wood chips at least 20 cm in depth and maintaining it in good condition until construction is complete.
- Placing medium weight geotextile cloth over the area to be used and installing a layer of crushed rock to a depth of 15 cm over top.
- Placing two layers of 19mm plywood.
- Placing steel plates.

Demolition of the Existing Buildings: The demolition of the existing houses, driveways, and any services that must be removed or abandoned, must take the critical root zone of the trees to be retained into account. If any excavation or machine access is required within the critical root zones of trees to be retained, it must be completed under the supervision and direction of the project arborist. If temporarily removed for demolition, barrier fencing must be erected immediately after the supervised demolition.

Paved Surfaces Above Tree Roots:

If the new paved surfaces within the CRZ of tree to be retained require excavation down to bearing soil and roots are encountered in this area, this could impact their health and structural stability. If tree retention is desired, a raised and permeable paved surface should be constructed in the areas within the critical root zone of the trees. The "paved surfaces above root systems" diagram and specifications is attached.

The objective is to avoid root loss and to instead raise the paved surface and its base layer above the roots. This may result in the grade of the paved surface being raised above the existing grade (the amount depending on how close roots are to the surface and the depth of the paving material and base layers). Final grading plans

should take this potential change into account. This may also result in soils which are high in organic content being left intact below the paved area.

To allow water to drain into the root systems below, we also recommend that the surface be made of a permeable material (instead of conventional asphalt or concrete) such as permeable asphalt, paving stones, or other porous paving materials and designs such as those utilized by Grasspave, Gravelpave, Grasscrete and open-grid systems.

Mulching: Mulching can be an important proactive step in maintaining the health of trees and mitigating construction related impacts and overall stress. Mulch should be made from a natural material such as wood chips or bark pieces and be 5-8cm deep. No mulch should be touching the trunk of the tree. See "methods to avoid soil compaction" if the area is to have heavy traffic.

Blasting: Care must be taken to ensure that the area of blasting does not extend beyond the necessary footprints and into the critical root zones of surrounding trees. The use of small low-concussion charges and multiple small charges designed to pre-shear the rock face will reduce fracturing, ground vibration, and overall impact on the surrounding environment. Only explosives of low phytotoxicity and techniques that minimize tree damage should be used. Provisions must be made to ensure that blasted rock and debris are stored away from the critical root zones of trees.

Scaffolding: This assessment has not included impacts from potential scaffolding including canopy clearance pruning requirements. If scaffolding is necessary and this will require clearance pruning of retained trees, the project arborist should be consulted. Depending on the extent of pruning required, the project arborist may recommend that alternatives to full scaffolding be considered such as hydraulic lifts, ladders or platforms. Methods to avoid soil compaction may also be recommended (see "Minimizing Soil Compaction" section).

Landscaping and Irrigation Systems: The planting of new trees and shrubs should not damage the roots of retained trees. The installation of any in-ground irrigation system must take into account the critical root zones of the trees to be retained. Prior to installation, we recommend the irrigation technician consult with the project arborist about the most suitable locations for the irrigation lines and how best to mitigate the impacts on the trees to be retained. This may require the project arborist supervise the excavations associated with installing the irrigation system. Excessive frequent irrigation and irrigation which wets the trunks of trees can have a detrimental impact on tree health and can lead to root and trunk decay.

Arborist Role: It is the responsibility of the client or his/her representative to contact the project arborist for the purpose of:

- Locating the barrier fencing
- Reviewing the report with the project foreman or site supervisor
- Locating work zones, where required
- Supervising any excavation within the critical root zones of trees to be retained
- Reviewing and advising of any pruning requirements for machine clearances

Review and site meeting: Once the project receives approval, it is important that the project arborist meet with the principals involved in the project to review the information contained herein. It is also important that the arborist meet with the site foreman or supervisor before any site clearing, tree removal, demolition, or other construction activity occurs and to confirm the locations of the tree protection barrier fencing.

10. DISCLOSURE STATEMENT

This arboricultural field review report was prepared by Talbot Mackenzie & Associates for the exclusive use of the Client and may not be reproduced, used or relied upon, in whole or in part, by a party other than the Client without the prior written consent of Talbot Mackenzie & Associates. Any unauthorized use of this report, or any part hereof, by a third party, or any reliance on or decisions to be made based on it, are at the sole risk of such third parties. Talbot Mackenzie & Associates accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report, in whole or in part.

Arborists are professionals who examine trees and use their training, knowledge, and experience to recommend techniques and procedures that will improve a tree's health and structure or to mitigate associated risks. Trees are living organisms whose health and structure change and are influenced by age, continued growth, climate, weather conditions, and insect and disease pathogens. Indicators of structural weakness and disease are often hidden within the tree structure or beneath the ground. The arborist's review is limited to a visual examination of tree health and structural condition, without excavation, probing, resistance drilling, increment coring, or aerial examination. There are inherent limitations to this type of investigation, including, without limitation, that some tree conditions will inadvertently go undetected. The arborist's review followed the standard of care expected of arborists undertaking similar work in British Columbia under similar conditions. No warranties, either express or implied, are made as to the services provided and included in this report.

The findings and opinions expressed in this report are based on the conditions that were observed on the noted date of the field review only. The Client recognizes that passage of time, natural occurrences, and direct or indirect human intervention at or near the trees may substantially alter discovered conditions and that Talbot Mackenzie & Associates cannot report on, or accurately predict, events that may change the condition of trees after the described investigation was completed.

It is not possible for an Arborist to identify every flaw or condition that could result in failure nor can he/she guarantee that the tree will remain healthy and free of risk. The only way to eliminate tree risk entirely is to remove the entire tree. All trees retained should be monitored on a regular basis. Remedial care and mitigation measures recommended are based on the visible and detectable indicators present at the time of the examination and cannot be guaranteed to alleviate all symptoms or to mitigate all risk posed.

Immediately following land clearing, grade changes or severe weather events, all trees retained should be reviewed for any evidence of soil heaving, cracking, lifting or other indicators of root plate instability. If new information is discovered in the future during such events or other activities, Talbot Mackenzie & Associates should be requested to re-evaluate the conclusions of this report and to provide amendments as required prior to any reliance upon the information presented herein.

11. IN CLOSING

We trust that this report meets your needs. Should there be any questions regarding the information within this report, please do not hesitate to contact the undersigned.

Yours truly,

Talbot Mackenzie & Associates

Prepared by:

Noah Talbot, BA


ISA Certified Arborist PN – 6822A Tree Risk Assessment Qualification Email: tmtreehelp@gmail.com

12. REFERENCES

Dunster, J.A., E.T. Smiley, N. Matheny, and S. Lily. 2017. Tree Risk Assessment Manual, International Society of Arboriculture (ISA).

The City of Victoria Tree Preservation Bylaw No. 05-106.

APPENDIX A - TREE MANAGEMENT PLAN (T1)



LEGEND

Existing tree with tag or ID #

Dripline radius (m)

─Tree protection fencing `Critical root zone radius (m)




Unsurveyed tree

Non-bylaw undersize tree

Site boundary

TREE PROTECTION FENCING



TREE PROTECTION FENCING

- FENCE WILL BE CONSTRUCTED USING 38 mm X 89mm WOOD FRAME: TOP, BOTTCM AND POSTS * USE CRANGE SNOW-FENCING MESH AND SECURE THE WOOD FRAME WTH*ZIP* TIES OR GALVANIZED STAPLES.
- ATTACH A 500mm X 500mm SIGN WITH THE FOLLOWING WORDING: PROTECTED FOOT ZONE - NO ENTRY. THIS SIGN MUST BE AFFIXED ON EVERY FENCE OR AT LEAST EVER 101 INSER MISTERS.
- IN ROCKY AREAS, METAL POSTS (T-BAR OR REBAR) DRILLED INTO ROCK WILL BE

Tree Management Plan- T1
Victoria Press Building
2621 Douglas Street
Victoria. BC

DATE: Decmeber 16, 2020
PREPARED FOR: Merchant House Capital
SCALE: 1: 500 @ 11" X 17"
DRAWN BY: NT
REVISION: 0


TALBOT MACKENZIE & ASSOCIATES

CONSULTING ARBORISTS
BOX 48153
VICTORIA, BC, V82 7H2
TEL: 250-479-8733
EMAIL: thtreehelp@gmail.com
www.treeheb.ca


APPENDIX B - PHOTOGRAPHS



Photograph 1. City trees NT1, NT2 & NT3 located on the Kings Road frontage.



Photograph 2 – City trees NT4, NT5 & NT6 located on the Kings Road frontage.




Photograph 3 – Yellow arrows indicate location of onsite plum trees 1898 (front), and 1899 (back).



Photograph 4 – Closeup of root collar and existing growing conditions of onsite plum (tag# 1898).



Photograph 5 – Yellow arrow indicates existing growing conditions and structure of onsite plum (tag# 1899).



Photograph 6 – Yellow arrow indicates location of non-bylaw protected size crabapple (tag# 1900).




Photograph 7 – Yellow arrow indicates location of onsite Japanese maple (tag# 1901).




Photograph 8 – Yellow arrow indicates location of onsite Japanese maple (tag# 1902).

APPENDIX C – LANDSCAPE PLANS




L1 Scale: 1:150

2 Grading and Imga



NOT FOR CONSTRUCTION

| MING NOTES D NOT SCALE DRAWING: VERIFY ALL PROPERTY LINES AND EXISTING PROTEINESVERSENCY OF DECOMMENCING WORK IN AN INGUIND MENTERSON AND ALL DEFAUL INSTINCTION. | LIMETRES. ANTIQUATITIES ON PLANS SHALL TAKE PRECEDENCE OVER PLANT LIST ANTIQUATITIES. |
|--|---|
| WING NOTES > NOT SCALE DRAWING: VERIFY PUCTURES/VEGETATION TO RE ID AN AND MICHAELING IN METERS | LLMETRES ANT QUANTITIES ON PLANS SHA LANTITIES |



APPENDIX D - SITE SERVICING PLAN

