


Attachment B:

Ship Point Pier Existing Condition Photos



View through hole in hollow timber pile



Damaged timber beam



Damage to timber decking



Suspended Services below pier



Deteriorated timber retaining wall



Pier Closure