

1351 Vining Street Site Photos



Fig. 1: Existing studio



Fig. 2: East elevation with living area window and neighbours fence.



Fig. 3: Fence and mature tree on property outside of living area window



Fig. 4-5: East elevation showing small bathroom window



Fig. 6: West elevation showing french doors, kitchen window, outdoor space, and neighbours 6 foot fence.



Fig. 7: Kitchen window on west elevation