



<section-header><section-header><list-item><list-item><list-item><list-item><list-item><list-item><list-item>





















13

Crystal Pool and Fitness Centre Maintenance

- HVAC system deficiencies identified in March 2020
- System not properly ventilating vapour from pool disinfection process
- · Potential risk to occupants if not addressed
- Plan to replace several components of the system over the next 5-6 months

© © </ 0

 Total cost \$487K will be funded by existing budgets

forp