E.1.a.g1210 Topaz Avenue: Development Variance Permit Application No. 00264 (Hillside - Quadra)

Councillor Dubow withdrew from the meeting at 5:09 p.m. due to a non-pecuniary conflict of interest.

Moved By Councillor Isitt **Seconded By** Councillor Thornton-Joe

That Council, after giving notice and allowing an opportunity for public comment at a meeting of Council, consider the following motion:

"That Council authorize the issuance of Development Variance Permit Application No. 00264 for 1210 Topaz Avenue, in accordance with:

- 1. Plans date stamped April 23, 2021.
- 2. Development meeting all Zoning Regulation Bylaw requirements, except for the following variances:
 - i. reduce the rear yard setback from 18.3m to 8.58m;
 - ii. reduce the east side yard setback from 4.97m to 2.19m; and
 - iii. reduce the number of vehicle parking from 36 stalls to 35 stalls.
- 3. The Development Permit lapsing two years from the date of this resolution."

CARRIED UNANIMOUSLY

Councillor Dubow returned to the meeting at 5:10 p.m.

F.1 <u>1210 Topaz Avenue: Development Variance Permit Application No. 00264</u> (Hillside - Quadra)

Committee received a report dated April 29, 2021 from the Director of Sustainable Planning and Community Development regarding information, analysis and recommendations for a Development Variance Permit Application for the property located at 1210 Topaz Avenue.

Councillor Dubow withdrew from the meeting at 1:20 p.m. due to a non-pecuniary conflict of interest with the following item as he has been a volunteer at an organization located at the site in question.

Moved By Councillor Isitt Seconded By Councillor Thornton-Joe

That Council, after giving notice and allowing an opportunity for public comment at a meeting of Council, consider the following motion:

"That Council authorize the issuance of Development Variance Permit Application No. 00264 for 1210 Topaz Avenue, in accordance with:

- 1. Plans date stamped April 23, 2021.
- 2. Development meeting all Zoning Regulation Bylaw requirements, except for the following variances:
 - i. reduce the rear yard setback from 18.3m to 8.58m;
 - ii. reduce the east side yard setback from 4.97m to 2.19m; and
 - iii. reduce the number of vehicle parking from 36 stalls to 35 stalls.
- 3. The Development Permit lapsing two years from the date of this resolution."

CARRIED UNANIMOUSLY



Committee of the Whole Report For the Meeting of May 13, 2021

To: Committee of the Whole **Date:** April 29, 2021

From: Karen Hoese, Director, Sustainable Planning and Community Development

Subject: Development Variance Permit Application No. 00264 for 1210 Topaz Avenue

RECOMMENDATION

That Council, after giving notice and allowing an opportunity for public comment at a meeting of Council, consider the following motion:

"That Council authorize the issuance of Development Variance Permit Application No. 00264 for 1210 Topaz Avenue, in accordance with:

- 1. Plans date stamped April 23, 2021.
- 2. Development meeting all *Zoning Regulation Bylaw* requirements, except for the following variances:
 - i. reduce the rear yard setback from 18.3m to 8.58m;
 - ii. reduce the east side yard setback from 4.97m to 2.19m; and
 - iii. reduce the number of vehicle parking from 36 stalls to 35 stalls.
- The Development Permit lapsing two years from the date of this resolution."

LEGISLATIVE AUTHORITY

In accordance with Section 498 of the *Local Government Act*, council may issue a Development Variance Permit that varies a *Zoning Regulation Bylaw* provided the permit does not vary the use or density of land from that specified in the *Zoning Regulation Bylaw*.

EXECUTIVE SUMMARY

The purpose of this report is to present Council with information, analysis and recommendations for a Development Variance Permit Application for the property located at 1210 Topaz Avenue. The proposal is to construct new additions to the Temple's existing kitchen and entrance. The variances are related to reducing the rear setback, reducing the east side yard setback, and reducing the vehicle parking.

The following points were considered in assessing this application:

- reducing the rear yard setback from 18.3m to 8.58m is considered supportable as the setback would still be located further back from the existing legal non-conforming setback associated with another portion of the building
- reducing the east side yard setback from 4.97m to 2.19m is considered supportable as it is a small addition and represents a similar setback to the existing condition
- reducing the vehicle parking from 36 stalls to 35 stalls is considered supportable as it is minimal in nature and the applicant proposes new short-term bicycle parking.

BACKGROUND

Description of Proposal

The proposal is to construct new additions to the Temple's existing kitchen and entrance. The proposed variances are related to:

- reducing the rear yard setback from 18.3m to 8.58m;
- reducing the east side yard setback from 4.97m to 2.19m; and
- reducing the number of vehicle parking from 36 stalls to 35 stalls.

Sustainability

The applicant has not identified any sustainability features associated with this proposal.

Active Transportation

The application proposes twelve short term bicycle stalls which support active transportation.

Public Realm

No public realm improvements beyond City standard requirements are proposed in association with this Development Permit Application.

Accessibility

The *British Columbia Building Code* regulates accessibility as it pertains to buildings. An existing lift allows those with limited mobility to avoid the stairs leading to the entrance.

Existing Site Development

The site is presently a two storey Sikh Temple operated by the Khalsa Diwan Society of Victoria.

Data Table

The following data table compares the proposal with the existing R1-B Zone, Single Family Dwelling District. An asterisk is used to identify where the proposal does not meet the requirements of the existing Zone. Two asterisks are used to identify a legal non-conforming condition.

Zoning Criteria	Proposal	Existing R1-B Zone (Public Buildings)
Site area (m²) – minimum	3030	460
Total floor area (m²) – maximum	N/A	N/A
Lot width (m) – minimum	49.74	15
Storeys – maximum	2	2.5
Site coverage (%) – maximum	34	40
Setbacks (m) – minimum		
Front (Arthur Road)	26.3	7.5
Rear (Topaz Avenue)	6.7 (existing) ** 8.58 (proposed) *	18.3
Side (east)	2.5 (existing) ** 2.19 (proposed) *	4.97
Side (Blackwood Street)	11.3	4.97
Combined side yards	7.46	4.5
Parking – minimum	35 *	36
Bicycle parking stalls - minimum		
Long Term	0	0
Short Term	12	1

Community Consultation

Consistent with the Community Association Land Use Committee (CALUC) Procedures for Processing Rezoning and Variance Applications, on March 25, 2021 the application was referred for a 30-day comment period to the Hillside-Quadra CALUC. At the time of writing this report, a letter from the CALUC had not been received.

This application proposes variances; therefore, in accordance with the City's *Land Use Procedures Bylaw*, it requires notice, sign posting and a meeting of Council to consider the variances.

ANALYSIS

Hillside-Quadra Neighbourhood Plan

The *Hillside-Quadra Neighbourhood Plan* identifies the subject site as "Place of Worship". However, there are no specific policies in the Plan that relate to the subject site.

Tree Preservation Bylaw and Urban Forest Master Plan

There are no *Tree Preservation Bylaw* and no impacts to public trees with this application.

Regulatory Considerations

There are three variances associated with the proposal. An addition to the main entrance requires a variance to the rear yard setback (Topaz Avenue), reducing it from 18.3m to 8.58m. This variance is considered supportable as the frontage along Topaz Avenue acts as the side yard of the property, whereas the *Zoning Regulation Bylaw* identifies the Topaz Avenue frontage as the rear yard. In addition, the addition is still set further back from the property line than an existing portion of the building that has a legal non-conforming setback of 6.7m.

The second variance relates to the expansion of the existing kitchen. A variance is required to reduce the east side yard setback from 4.97m to 2.19m, which is considered supportable as it is a small addition and represents a similar setback to the existing condition of 2.5m.

Finally, the additional floor area increases the parking requirement, and a variance is therefore required to reduce the vehicle parking from 36 stalls to 35 stalls. This variance is considered supportable as it is minimal in nature and the applicant proposes new short-term bicycle parking. In addition, the applicant has reconfigured the parking which has removed a previous encroachment of the parking stalls onto Arthur Avenue.

CONCLUSIONS

The proposal to reduce the rear and east side yard setbacks and to reduce the vehicle parking is considered supportable, as the variances represent minimal changes from existing conditions and allow for small expansions to the institutional building. It is therefore recommended that Council consider supporting the application.

ALTERNATE MOTION

That Council decline Development Variance Permit Application No. 00264 for the property located at 1210 Topaz Avenue.


Respectfully submitted,

Mike Angrove Senior Planner Development Services Division Karen Hoese, Director
Sustainable Planning and Community
Development Department

Report accepted and recommended by the City Manager.

List of Attachments

- Attachment A: Subject Map
- Attachment B: Aerial Map
- Attachment C: Plans date stamped April 26, 2021
- Attachment D: Letter from applicant to Mayor and Council dated March 17, 2021
- Attachment E: Tree Preservation Plan dated October 28, 2020.





1210 Topaz Avenue Development Variance Permit No:00264









ATTACHMENT C

Site Plan Of: Lot C (DD 337713i). Block 14. Section 4. Victoria District, Plan 299.

C Lamp Standard

Dated this 5th day of March, 2020.

Distances and elevations shown are in metres

AVERAGE GRADE CALCULATIONS:

GRADE POINTS:		GRADE POINTS:	AVERAGE OF POINTS :	DISTANCE BETWEEN POINTS:	TOTALS:
GRADE POINT A: GRADE POINT B: GRADE	47,00 M 47,30 M 45,70 M 45,50 M 45,30 M 45,30 M 45,30 M 45,30 M 45,30 M 45,30 M 46,30 M 46,	GRADE POINT 'A 8 PC GRADE POINT '8 8 CC GRAD 'CC GRA	47 (00 + 77 (00) 77 (0	x 13.167 M x 11.481 M x 15.628 M x 0.560 M x 5.160 M x 5.180 M x 1.219 M x 1.220 M x 1.220 M x 1.232 M x 1.252 M x 1.252 M x 1.252 M x 1.252 M x 1.252 M x 1.252 M x 2.252 M x 2.252 M x 1.455 M x 4.950 M x 6.850 M	= 620.82 = 533.86 = 712.54 = 25.48 = 55.46 = 55.46 = 82.80 = 963.54 = 872.44 = 872.44 = 82.80 = 288.39 = 171.48 = 123.23 = 63.65 = 218.05 = 218.05 = 159.86 = 169.86 = 218.05 = 159.86 = 140.71
		I	TOTALS	166.934 M	7 571.75

GRADE CALCULATION: 7 571.75 / 166.934 = 45.357 M








EXISTING BUILDING NEW ADDITION

REVISIONS AS PER APPLICATION REVIEW SUMMARY



Blackwood Street



Wey Mayenburg Land Surveying Inc. WWW.Weysurveys.com #4-2227 James White Boulevard Sidney, BC V8L 125 Telephone (250) 656-6156 File: 200089ISTIGH

DESIGN DATA:

LEGAL: LOT 'C', (DD 337713i) BLOCK 14, SECTION 4, VICTORIA DISTRICT. PLAN 299. P.I.D. 008-618-500

CIVIC ADDRESS: 1210 Topaz Avenue, Victoria, B.C.

R 1B ZONING:

SITE AREA: 3 030.00 sq. m. (32 615.715 sq. ft.) GROSS FL. AREA: MAIN FL. - EXISTING = 747.618 sq. m. ADDITION = 68.422 sq. m.

2ND FL. - EXISTING = 615.730 sq. m. (CARETAKER SUITE = 65.17 sq. m.) ADDITION = 100.210 sq. m.

EXISTING = 1 363,348 sq. m. ADDITION = 168.632 sq. m. TOTAL = 1 501,980 sq. m. (16 167.707 sq. ft.) TOTAL GFA:

LOT WIDTH: 33 m and 49.4 m (exist.)

HEIGHT: Existing (no change) 11 m, 2 1/2 storeys permitted

PERMITTED USE: Public Building

SITE COVERAGE: Max. 40% Permitted Provided = Including decks (958.34 sq. m.) (29.38 %)

SETBACKS: Front yard (Arthur Ave.) = 26.3 m (exist'g no change)
Rear Yard (Topaz Ave.) 25% of Lot Depth = 18.3 m
- Exist = 6.7 m (non conforming).
(variance of 11.6 M reg'd.)

Interior Side Yard 10% of lot width = 4.974 m - Proposed = 2.3 m / 0.792 (non conforming). (variance of 4.182 M reg'd.)

Combined Side Yard = 4.5 m - New = 7.568 m / 6.06 m

Exterior Side Yard (Blackwood Ave.) 10% of Lot Width = 4.974 m $^{\circ}$ New = 5.288 m $^{\circ}$

EAVES PROJECTION: 0.75 m (Exist. no change)

PARKING: REQUIRED: (1393.73/40) = 34.843 CAR STALLS CARETAKER = 1 STALL TOTAL = 35.843 OR 36 STALLS PROVIDED: 33+2 STALLS includes 1 HC STALL (variance of 1.act stall regid).

BICYCLE PARKING: REQUIRED: (1364.767/200) = 6.82 BICYCLES PROVIDED SHORT TERM = 12 BICYCLES







GENERAL NOTES


- 1. ALL SURVEY INFORMATION AND EXISTING CONDITIONS ARE TAKEN FROM SITE SERVICES
- DRAWING PROVIDED BY WEY MAYENBURG LAND SURVEYING INC. DATED MAR. 5, 2020.


 2. REFER TO SOIL REPORT FROM MGE SERVICES INC. GEOTECH CONSULTANT.
- CONTRACTOR TO VERIFY ALL DIMENSIONS AND GRADE ELEVATIONS ON SITE BEFORE PROCEEDING WITH THE WORK AND CO-ORDINATE THE WORK OF ALL SUBTRADES. FOR INCONSISTENCIES CONTACT THE CONSULTANTS.
- 3. ALL WORK IS REQUIRED TO BE DONE AS PER PRESENT B.C.BUILDING CODE


PROPOSED ADDITIONS AND ALTERATIONS TO EXISTING SIKH TEMPLE	ON 1210 TOPAZ AVENUE,	VICTORIA ,B.C.	FOR KHALSA DIWAN SOCIETY OF VICTORIA	
			PKM	
DATA			DRAWN	
SITE PLAN & DESIGN DATA		SCALE: AS NOTED	APR. 23, 2019	



PROJECT NO. 19:04 A-1











ADDITIONS AND ALTERATIONS TO EXISTING SIKH TEMPLE ON 1210 TOPAZ AVENUE,


ROOF PLAN


PROJECT NO. 16:06

A-4
















ADDITIONS AND ALTERATIONS TO EXISTING SIKH TEMPLE ON 1210 TOPAZ AVENUE,	VICTORIA , B.C.	PKM FOR KHALSA DIWAN SOCIETY OF VICTORIA
		DRAWN PKM
MAIN FLOOR PLAN	SCALE : AS NOTED	JUNE 10, 2019 D

Protection Engineering 202 - 2000 Artisus Smeet AMACOLVER, BRITTING COLLAMBIA ZAMAGA, VIGI 3799 Tel: 804.688-0388 Tel: 804.688-0388 Tel: 804.688-0388 Tel: 804.688-0388		
CAMACIA, V6J 3Y9 Tet: 604,683-0306 Fair: 604,683-0305	Protection E	
	Tel: 604.682-036 Tel: 604.682-633	Y9 16 15 Hey-Toda Corondorno
	DATE: Jan. 08, 2021	DRAWN: PID JOB#: 09-2382
		CHECKED: BM
Jan. 08, 2021 JOB#: 09-2382 CHECKED:		drawing no.: CC-1









2nd FLOOR PLAN	3 PLAN		PROPOSED ADDITIONS AND ALTERATIONS TO EXISTING SIKH TEMPLE
			ON 1210 TOPAZ AVENUE,
SCALE: AS NOTED			MCTORIA ,B.C.
JUNE 10, 2019	DRAWN	PKM	PKM FOR KHALSA DIWAN SOCIETY OF VICTORIA

Frotection E 302 - 2020 / VARCOLVER, BR CHACA, VEJ 3	Engineering Visital Street Irish COLUMBIA					
Tel: 804.882-9388 Fec: 804.882-9325 Fe-18: 9090-9 54890-909 (smallers)						
, broad to	Jan. 06, 2021					
DATE: Jan. 08, 2021	DRAWN: PID JOB#: 09-2382					
	CHECKED: BM					
	drawing no.: CC-2 2 of: 2					



City of Victoria 1 Centennial Square Victoria, BC

March 17, 2021

RE: Development Variance Permit for 1210 Topaz Avenue

Dear Mayor and Council,

I am writing to you today on behalf of the Khalsa Diwan Society of Victoria ("the Society") regarding the Sikh Temple located at 1210 Topaz Avenue. The Temple, originally built in 1969, recently received provincial funding to renovate the building to improve the experience of community members using the facilities. The renovation is primarily to accommodate the growing Sikh community and update important features. The kitchen is being expanded, as is the front of the building to accommodate the men's and women's shoe rooms. The front entrance has been expanded to provide larger gathering space for weddings. The kitchen expansion is especially important to the Society, as it is used by volunteers in the Sikh community to prepare food to be donated to Our Place Society, as well as to the Red Cedar Café during the COVID-19 Pandemic.

These renovations/changes have triggered the need for a Development Variance Permit, primarily a parking variance and several setback variances. We believe that these variances are supportable and will result in little significant change to the design, character, and impact of the building on the surrounding properties and streets. Additionally, dealing with these variances now are rectifying several historical issues and will bring the site into compliance with City of Victoria policies.

A Building Permit application was previously submitted for this project, but response from staff indicated a need for review. Most outstanding issues can be resolved via the BP, but several require a DVP. The variances requested through this DVP are as follows:

Table 1: Summary of Variances requested

	Required	Provided	Variance Requested
Parking	36 Stalls	35 stalls	1 stall
Setbacks - rear	25% of Lot Depth or	6.7m (non-conforming)	11.6m
yard	18.3m		
Setbacks - interior	10% of lot width or	2.3m / 0.795m	4.179m
side yard	4.974		

- A **1 stall parking variance.** 36 stalls are required for this site, and 35 have been provided. This variance is required for several reasons: a slight reconfiguration of parking to allow for renovations/an addition to the building, and to better align the parking configuration with non-conforming rights from 1969 plans and Schedule C, where the 1969 plans cannot be met. We believe the variance is justifiable because parking has historically not been an issue at this site. When overflow parking is required, patrons will often use street parking, but there have been no reports of this being an issue with neighbours or the wider community.
- A 4.179m setback variance on the interior side yard (east side of the building) and a 11.6m setback variance for the rear yard (Topaz Ave). Setbacks on both these side were historically nonconforming. Granting the requested setbacks would rectify the historical issue as well as allow for the required renovations. These variances will have little to no impact on neighbouring properties or on the street/pedestrian experience.

Rectifying historic issues will bring the site plans for the Temple into better alignment with City of Victoria policies, and we believe the requested variances are justifiable due to their minimal impacts on the site and on neighbours. The Society is eager to complete these renovations, as it will allow them to refocus efforts on some of their community service activities, such as food preparation for Victoria's homeless population and providing affordable housing rentals in the neighbourhood. Several of their properties in the neighbourhood require updating, which will be pursued after the Temple renovations are complete.

Thank you for considering this application.

Sincerely,

Kaeley Wiseman

Kaeley Wiseman, RPP, MCIP, PMP Principal, Wiser Projects p. 250.580.3835 e. kaeley@wiserprojects.com



Talbot Mackenzie & Associates

Consulting Arborists

1210 Topaz Ave.—Victoria, BC

Construction Impact Assessment & Tree Preservation Plan

Prepared For: Bob Gill

Pacific Concept Developments Ltd.

4275 Faithwood Road Victoria, BC V8X 5C6

Prepared By: Talbot, Mackenzie & Associates

Robert McRae

ISA Certified # PN-7125A

TRAQ – Qualified

Date of Issuance: October 28, 2020

Box 48153 RPO - Uptown Victoria, BC V8Z 7H6

Ph: (250) 479-8733 Fax: (250) 479-7050 Email: tmtreehelp@gmail.com



Talbot Mackenzie & Associates

Consulting Arborists

Jobsite Property: 1210 Topaz Avenue; Victoria, BC

Date of Site Visit(s): October 26, 2020

Site Conditions: No ongoing construction activity.

SUMMARY

• The proposal includes demolition the existing prep kitchen, construction of a new prep kitchen (excavating to match existing kitchen lobby grade), as well as construction of a new stairwell and sidewalk within the CRZs of bylaw protected trees on the boundary of or within Summit Park.

• One tree has been identified "To Be Determined." Each of the remaining two trees and two seedlings have been identified for retention, provided the mitigation measures outlined in this report are followed.

SCOPE OF ASSIGNMENT

- Inventory the existing bylaw protected trees and any trees on municipal or neighbouring
 properties that could potentially be impacted by construction or that are within three metres of
 the property line.
- Review the proposal to demolish the existing prep kitchen, construct a new prep kitchen (excavation to match existing kitchen lobby grade), as well as construct a new stairwell and sidewalk within the CRZs of bylaw protected trees on the boundary of or within Summit Park.
- Comment on how construction activity may impact existing trees.
- Prepare a tree retention and construction damage mitigation plan for those trees deemed suitable to retain given the proposed impacts.

METHODOLOGY

- We visually examined the trees on the property and prepared an inventory in the attached Tree Resource Spreadsheet.
- Each bylaw protected tree was previously identified using a numeric metal tag attached to its lower trunk. Park trees were not tagged.
- Information such as tree species, DBH (1.4m), crown spread, critical root zone (CRZ), health, structure, and relative tolerance to construction impacts were included in the inventory.

- The conclusions reached were based on the information provided within the attached plans from MISRA Architect Ltd. (dated June 10, 2019).
- A Tree Protection Site Plan was created using the Site Plan Provided.

LIMITATIONS

- No exploratory excavations have been conducted and thus the conclusions reached are based solely on critical root zone calculations, observations of site conditions, and our best judgement using our experience and expertise. The location, size and density of roots are often difficult to predict without exploratory excavations and therefore the impacts to the trees may be more or less severe than we anticipate.
- The extent of impacts to some trees will largely depend on the cut-slope prescribed by the geotechnical engineer during excavation for the foundations. Therefore, the proximity of excavation to trees (without shoring) can only be estimated and may be closer or farther from trees than we estimate.
- No servicing plans or locations were provided for this assessment. The installation of hydro, telecommunications, storm, water and sanitary sewer services could result in additional tree impacts.

SUMMARY OF TREE RESOURCE

• 1 tree was inventoried on the subject property (likely shared ownership), with an additional 2 trees and 2 seedlings within 3m of the property line in the adjacent Summit Park. All are Garry Oaks (*Quercus garryana*).

POTENTIAL IMPACTS TO TREES

- We expect the greatest potential for impacts to trees will occur during:
 - 1) Construction of the retaining wall and stairwell within the CRZ of Garry Oak #154; 67cm DBH, and Garry Oak NT#2, 49cm DBH.
 - 2) Excavation for the new prep kitchen as deep as -2.134m within the CRZ of #154.
 - 3) Demolition of the existing prep kitchen within the CRZ of #154.
 - 4) Construction of the new sidewalk within the CRZ of #154, NT#2, and Garry Oak NT#1; 25cm DBH.

RETAINING WALL/STAIRWELL

• Garry Oak #154 grows within 2.5m of the existing prep kitchen, at 47.5m elevation, according to the site plan provided. The top of stair/retaining wall elevation shows as 47.48m finished grade, resulting in minimal grade changes within 2m of the tree. Bottom of stairs finished

grade shows as 45.32m, a -2.16m change over a span of 3.073m. Additional excavation within the CRZ may be required outside the retaining wall—we recommend that this be limited to 0.5m at the bottom of the stairs and minimal at the top, as it is likely that roots from #154 will be encountered here. We also recommend the project arborist supervise the excavation and make the tree's final retention determination at that time. Small machinery will also be recommended.

Roots from NT#2 could be restricted (due to the presence of #154) to the west, and is likely retainable if mitigation measures for #154 are followed.

PREP KITCHEN DEMOLITION AND CONSTRUCTION

• Excavation for the new prep kitchen will occur within the CRZ of #154, to a finished grade of 45.47m, a difference of -2.03m from the 47.5m elevation at the tree. The foundation will be constructed at 2.5m from the tree. However, if a cut-slope prescribed by the geotechnical engineer, excavation may be required further into the CRZ. We recommend this excavation be limited to 0.5m outside the foundation. The project arborist should supervise this excavation as well as the demolition of the existing foundation, as roots are likely to be encountered in this area.

SIDEWALK

• The new sidewalk east of the new prep kitchen is shown to be installed at 48.48m elevation, within the CRZs of #154, NT#1, and NT#2. Given the sidewalk edge is within 1m of #154, roots are likely to be encountered during excavation. We recommend the excavation be completed under the direction of the project arborist, and that the sidewalk be constructed from permeable surface materials (see "Paved Surfaces Above Tree Roots").

BARRIER FENCING

 Protective barrier fencing should be erected and maintained throughout the construction timeframe, located as close to the sidewalk and retaining wall as possible; approximately 0.75m west of the tree, to the north and south edges of the CRZ, ending at the east property fence.

MITIGATION MEASURES (FOR REFERENCE)

ARBORIST SUPERVISION

• All excavation occurring within the critical root zones of protected trees should be completed under the direction or supervision of the project arborist. This includes (but is not limited to) the following activities within CRZs:

- Excavation for the retaining wall/stairwell, foundations, and sidewalk.
- Demolition of the existing foundation.

PRUNING ROOTS

• Any severed roots must be pruned back to sound tissue to reduce wound surface area and encourage rapid compartmentalization of the wound. Backfilling the excavated area around the roots should be done as soon as possible to keep the roots moist and aid in root regeneration. Ideally, the area surrounding exposed roots should be watered; this is particularly important if excavation occurs or the roots are exposed during a period of drought. This can be accomplished in a number of ways, including wrapping the roots in burlap or installing a root curtain of wire mesh lined with burlap, and watering the area periodically throughout the construction process.

BARRIER FENCING

The areas surrounding the trees to be retained should be isolated from the construction activity
by erecting protective barrier fencing. Where possible, the fencing should be erected at the
perimeter of the critical root zones.

The barrier fencing must be a minimum of 4 feet in height, of solid frame construction that is attached to wooden or metal posts. A solid board or rail must run between the posts at the top and the bottom of the fencing. This solid frame can then be covered with plywood, or flexible snow fencing. The fencing must be erected prior to the start of any construction activity on site (i.e. demolition, excavation, construction), and remain in place through completion of the project. Signs should be posted around the protection zone to declare it off limits to all construction related activity. The project arborist must be consulted before this fencing is removed or moved for any purpose.

MINIMIZING SOIL COMPACTION

- In areas where construction traffic must encroach into the critical root zones of trees to be retained, efforts must be made to reduce soil compaction where possible by displacing the weight of machinery and foot traffic. This can be achieved by one or a combination of the following methods (depending on the size of machinery and the frequency of use):
 - Placing a layer of geogrid (such as Combigrid 30/30) over the area to be used and installing a layer of crushed rock to a depth of 15 cm over top or a layer of hog fuel or coarse wood chips at least 30 cm in depth and maintaining it in good condition until construction is complete.
 - Installing a layer of hog fuel or coarse wood chips at least 20 cm in depth and maintaining it in good condition until construction is complete.

- Placing two layers of 19mm plywood.
- Placing steel plates

MULCHING

Mulching can be an important proactive step in maintaining the health of trees and mitigating
construction related impacts and overall stress. Mulch should be made from a natural material
such as wood chips or bark pieces (not dyed) and be 5-8cm deep. No mulch should be touching
the trunk of the tree. See "methods to avoid soil compaction" if the area is to have heavy
traffic.

SCAFFOLDING

• This assessment has not included impacts from potential scaffolding including canopy clearance pruning requirements. If scaffolding is necessary and this will require clearance pruning of retained trees, the project arborist should be consulted. Depending on the extent of pruning required, the project arborist may recommend that alternatives to full scaffolding be considered such as hydraulic lifts, ladders or platforms. Methods to avoid soil compaction may also be recommended (see "Minimizing Soil Compaction" section).

ARBORIST ROLE

- It is the responsibility of the client or his/her representative to contact the project arborist for the purpose of:
 - Locating the barrier fencing
 - o Reviewing the report with the project foreman or site supervisor
 - o Locating work zones, where required
 - o Supervising any excavation within the critical root zones of trees to be retained
 - o Reviewing and advising of any pruning requirements for machine clearances

REVIEW AND SITE MEETING

Once the project receives approval, it is important that the project arborist meet with the
principals involved in the project to review the information contained herein. It is also
important that the arborist meet with the site foreman or supervisor before any site clearing,
tree removal, demolition, or other construction activity occurs and to confirm the locations of
the tree protection barrier fencing.

Please do not hesitate to call us at (250) 479-8733 should you have any further questions.

Thank you,

Allelae

Robert McRae ISA Certified # PN-7125A TRAQ – Qualified

Talbot Mackenzie & Associates ISA Certified Consulting Arborists

Attached:

1-page tree resource spreadsheet

1-page Tree Protection Site Plan

1-page construction site plan

2-page tree resource spreadsheet methodology and definitions

Disclosure Statement

The tree inventory attached to the Tree Preservation Plan can be characterized as a limited visual assessment from the ground and should not be interpreted as a "risk assessment" of the trees included.

Arborists are professionals who examine trees and use their training, knowledge and experience to recommend techniques and procedures that will improve their health and structure or to mitigate associated risks.

Trees are living organisms, whose health and structure change, and are influenced by age, continued growth, climate, weather conditions, and insect and disease pathogens. Indicators of structural weakness and disease are often hidden within the tree structure or beneath the ground. It is not possible for an Arborist to identify every flaw or condition that could result in failure or can he/she guarantee that the tree will remain healthy and free of risk.

Remedial care and mitigation measures recommended are based on the visible and detectable indicators present at the time of the examination and cannot be guaranteed to alleviate all symptoms or to mitigate all risk posed.


Inventory date: October 26, 2020 Tree Resource Spreadsheet - 1210 Topaz Avenue

Tree ID	Common Name	Latin Name	DBH (cm) ~ approximate	Crown Spread (diameter in metres)	CRZ (radius in metres)	Relative Tolerance (good, moderate, poor)	Health	Structure	Remarks and Recommendations	Bylaw Protected	Retention Status
154	Garry Oak	Quercus garryana	67.0	10.0	6.7	Good	Good	Hair	Some previous clearance pruning for building; canopy begins at ~6m.	Yes	TBD
NT1	Garry Oak	Quercus garryana	25.0	4.0	2.5	Good	Fair	Hair	Seam up lower trunk with active response growth, suppressed by 154. Past ~8cm and ~5cm limb failures.	Yes	Retain
NT2	Garry Oak	Quercus garryana	49.0	8.0	4.9	Good	Good	Fair	Canopy measured in one direction, lean south over existing building, past clearance pruning with good compartmentalization.	Yes	Retain
S1	Garry Oak	Quercus garryana	4 at caliper	1.0	0.5	Good	Good	Fair-poor	Seedling growing through chain-link fence.	Yes	Retain
S2	Garry Oak	Quercus garryana	4 at caliper	1.0	0.5	Good	Good	Good	Seedling.	Yes	Retain

Prepared by: Talbot Mackenzie & Associates ISA Certified and Consulting Arborists Phone: (250) 479-8733

Fax: (250) 479-7050

email: tmtreehelp@gmail.com



Site Plan Of: Lot C (DD 337713i), Block 14, Section 4,

Victoria District, Plan 299. P.I.D. 008-618-500

5 4 3 2 1 0 5 10 15

Scale = 1:200

Scale = 1:200

C Lamp Standard

Legend:

Detect this 5th day of March 20

Dated this 5th day of March, 2020.

Distances and elevations shown are in metres.

Elevations are based on geodetic datum CVD28BC and derived from OCM 25-147.

This site plan is for building and design purposes and is for the exclusive use of our client.

This document shows the relative location of the surveyed structures and features with respect to the boundaries of the parcel described above. This document shall not be used to define property lines or property corners.

The subject property is affected by the following registered documents: <u>233345G.</u>

LEGEND:

ROOM NO.

A WINDOW TYPE

20 DOOR TYPE

1 100 DETAILS

SECTION TYPE

ND NAPKIN DISPOSAL

TTD TOILET TISSUE DISPENSER

TTD TOILET TISSUE DISPENSER

TDD TOWEL DISPENSER / DISPOSAL

SD SOAP DISPENSER

WALL TYPE

1 ROOF & FLOOR TYPE

NAPKIN VENDOR

EXISTING BUILDING

NEW ADDITION



(IN METERS)

00.00 M

EXISTING GRADE

FIRERATING LEGEND :

EXIT DIRECTION SIGN

AVERAGE GRADE CALCULATIONS:

REFER TO DRAWING A-401

(45.40 + 45.40 + 43.60 + 43.70 + 43.70 + 44.20 + 44.40 + 47.00 + 47.30) / 9 = 44.966 M

- Exist. = 21.2 m/20.14 m (no change)
Exterior Side Yard (Blackwood Ave.) 10% of Lot Width = 4.94 m
- New = 11.301 m

EAVES PROJECTION: 0.75 m (Exist. no change)

Combined Side Yard = 4.5 m

TOTAL GFA:

PERMITTED USE: Public Building

SITE COVERAGE: Max. 40% Permitted

PARKING: Per Schedule 'C' (No change to occupant load or parking)

LOT 'C', (DD 337713i) BLOCK 14, SECTION 4, VICTORIA DISTRICT. PLAN 299. P.I.D. 008-618-500

ADDITION = 736.52 SQ. FT.

EXISTING = 15202.12 SQ. FT.

Existing (no change) 11 m, 2 1/2 storeys permitted

Provided = Including decks (958.34 sq. m.) (29.38 %)

- Exist = 8.1 m (non conforming)

- Exist = 3.5 m / 2.44 m (non conforming)

ADDITION = 1.487.18 SQ. FT.

750.66 SQ. FT.

1210 Topaz Avenue, Victoria, B.C.

32 615.715 sq. ft. (3 030.00 sq. m.)

2ND FL. - EXISTING = 7 005.29 SQ. FT.

ADDITION =

GROSS FL. AREA: MAIN FL. - EXISTING = 8 196.83 SQ. FT.

33 m and 49.4 m (exist.)

SETBACKS: Front yard (Arthur Ave.) = 26.3 m (exist'g no change)
Rear Yard (Topaz Ave.) 25% of Lot Depth = 18.3 m

Interior Side Yard 10% of lot width = 4.94 m

CODE ANALYSIS:

DESIGN DATA:

CIVIC ADDRESS:

LEGAL

ZONING:

SITE AREA:

LOT WIDTH:

HEIGHT:

REFERENCE : BRITISH COLUMBIA BUILDING CODE 2018 - 3.2.2.25 UP TO 2 STOREYS

USE AND OCCUPANCY : A2 (Single Occupancy)

BUILDING HEIGHT: 2 Storeys

STREET FACING: 2

BUILDING AREA: Max. Building area permitted Existing Building Area = 10 764.26 sq. ft. (1 000.00 sq. m.) = 8 209.95 sq. ft. (762.70 sq. m.)

Additional Building Area = 1 120.00 sq. ft. (104.05 sq. m.)

Total Building Area = 9 329.95 sq. ft. (866.75 sq. m.)

CONSTRUCTION : COMBUSTIBLE SPRINKLERS : no

OCCUPANT LOAD: 470 persons (no change)

FIRE SEPARATIONS: ROOF - 3/4 hr


FLOORS - 3/4 hr WALLS - 3/4 hr. Loadbearing walls & columns = 3/4 hr


WASHROOM FACILITIES: As per 3.7.2.2.(8) (no change)

GENERAL NOTES

- ALLSURVEY INFORMATION AND EXISTING CONDITIONS ARE TAKEN FROM SITE SERVICES
 DRAWING PROVIDED BY WEY MAYENBURG LAND SURVEYING INC. DATED MAR. 5, 2020.
 REFER TO SOIL REPORT FROM GEOTECH CONSULTANT.
- 2. CONTRACTOR TO VERIFY ALL DIMENSIONS AND GRADE ELEVATIONS ON SITE BEFORE PROCEEDING WITH THE WORK AND CO-ORDINATE THE WORK OF ALL
- SUBTRADES. FOR INCONSISTENCIES CONTACT THE CONSULTANTS.

 3. ALL WORK IS REQUIRED TO BE DONE AS PER PRESENT B.C.BUILDING CODE
- 2018, CITY OF VICTORIA BY-LAWS AND AUTHORITIES HAVING JURISDICTION.
- 4. ALL EXPOSED CONCRETE SURFACES TO BE PAINTED
- 5. ALL COLORS FOR CONCRETE SIDING, CONCRETE, EXPOSED STEEL AND INTERIOR WALLS ARE TO BE AS SELECTED BY THE CONSULTANT.6. CONTRACTORS TO COORDINATE WITH ALL CONSULTANT'S DRAWINGS BEFORE CONSTRUCTION.
- 7. ALL STAIRS HANDRAILS & GUARDRAILS TO COMPLY WITH BCBC 3.4.6.5.(9).
- 8. ALL COLD JOINTS IN CONCRETE SHALL BE WATERPROOFED AND TREATED WITH WATER STOPS (KRYTON OR EQUIVALENT).
- 9. PROVIDE SHOP DRAWINGS FOR WINDOWS, DOORS, HANDRAILS, MISCELLANEOUS METAL AND
- ELECTRICAL/MECHANICAL SYSTEMS FOR CONSULTANT'S REVIEW.
- 10.ALL GYPSUM BOARD SHALL BE TYPE 'X'.





NOTE:
This is a copyright drawing and shall not be reproduced or revised without written permission and must be returned at completion of work or upon request. The contractor shall check and verify all dimensions and report all errors and omissions to the architect. Drawings must not be scaled. This drawing shall not be used for construction purposes until so approved.



SITE PLAN

& DESIGN DATA
SCALE : AS NOTED


SCALE : AS NOTED

APR. 23, 2019
DRAWN PKM FOR KHALSA DIWAN SOCIETY OF VICTORIA


STEPLAN DATA
ADDITIONS AND ALTERATIONS
TO EXISTING
SIKH TEMPLE
ON 1210 TOPAZ AVENUE,

VICTORIA ,B.C.

PROJECT NO. 19:04 **A-101**



WWW.Weysurveys.com #4-2227 James White Boulevard Sidney, BC V8L 1Z5 Telephone (250) 656-5155 File: 200069\SIT\GH



Blackwood Street

Box 48153 RPO - Uptown Victoria, BC V8Z 7H6 Ph: (250) 479-8733 Fax: (250) 479-7050 Email: tmtreehelp@gmail.com

Tree Resource Spreadsheet Methodology and Definitions

<u>Tag</u>: Tree identification number on a metal tag attached to tree with nail or wire, generally at eye level. Trees on municipal or neighboring properties are not tagged.

NT: No tag due to inaccessibility or ownership by municipality or neighbour.

<u>DBH</u>: Diameter at breast height – diameter of trunk, measured in centimetres at 1.4m above ground level. For trees on a slope, it is taken at the average point between the high and low side of the slope.

- * Measured over ivy
- ~ Approximate due to inaccessibility or on neighbouring property

<u>Crown Spread</u>: Indicates the diameter of the crown spread measured in metres to the dripline of the longest limbs.

Relative Tolerance Rating: Relative tolerance of the tree species to construction related impacts such as root pruning, crown pruning, soil compaction, hydrology changes, grade changes, and other soil disturbance. This rating does not take into account individual tree characteristics, such as health and vigour. Three ratings are assigned based on our knowledge and experience with the tree species: Poor (P), Moderate (M) or Good (G).

Critical Root Zone: A calculated radial measurement in metres from the trunk of the tree. It is the optimal size of tree protection zone and is calculated by multiplying the DBH of the tree by 10, 12 or 15 depending on the tree's Relative Tolerance Rating. This methodology is based on the methodology used by Nelda Matheny and James R. Clark in their book "Trees and Development: A Technical Guide to Preservation of Trees During Land Development."

- 15 x DBH = Poor Tolerance of Construction
- 12 x DBH = Moderate
- 10 x DBH = Good

To calculate the critical root zone, the DBH of multiple stems is considered the sum of 100% of the diameter of the largest stem and 60% of the diameter of the next two largest stems. It should be noted that these measures are solely mathematical calculations that do not consider factors such as restricted root growth, limited soil volumes, age, crown spread, health, or structure (such as a lean).

Health Condition:

- Poor significant signs of visible stress and/or decline that threaten the long-term survival of the specimen
- Fair signs of stress
- Good no visible signs of significant stress and/or only minor aesthetic issues

Structural Condition:

- Poor Structural defects that have been in place for a long period of time to the point that mitigation measures are limited
- Fair Structural concerns that are possible to mitigate through pruning
- Good No visible or only minor structural flaws that require no to very little pruning

Retention Status:

- X Not possible to retain given proposed construction plans
- Retain It is possible to retain this tree in the long-term given the proposed plans and information available. This is assuming our **recommended mitigation measures are followed**
- Retain * See report for more information regarding potential impacts
- TBD (To Be Determined) The impacts on the tree could be significant. However, in the absence of exploratory excavations and in an effort to retain as many trees as possible, we recommend that the final determination be made by the supervising project arborist at the time of excavation. The tree might be possible to retain depending on the location of roots and the resulting impacts, but concerned parties should be aware that the tree may require removal.
- NS Not suitable to retain due to health or structural concerns

Development Variance Permit Application for 1210 Topaz Avenue







